

Operation Manual

MODEL EC 330

**Microcomputer Based
Conductivity /TDS
&Temperature Pocket
Meter**



EC330



CONTENTS


INITIAL INSPECTION AND ASSEMBLY	2
VISIONPLUS EC 330 OVERVIEW.....	2
A. Meter Description.....	2
B. LCD Display	2
OPERATION MODES AND KEYPAD OPERATIONS...	3
A. Operation Modes.....	3
B. Keypad Operations.....	3
BEFORE YOUR FIRST USE	4
A. Insert Batteries	4
B. Soak the Electrode....	4
C. Preparing Standard Solutions.....	4
D. Setup and Calibrate the Electrode and Meter.....	5
USING VISIONPLUS EC 330.....	5
A. Power on/off	5
B. Calibrate Conductivity.....	5
C. Measure	6
D. Hold Data	6
REPLACE ELECTRODE.....	6
REPLACE THE OLD BATTERIES.....	7
ERROR DISPLAYS AND TROUBLESHOOTING	8
SPECIFICATIONS	9
WARRANTY	10

INITIAL INSPECTION AND ASSEMBLY

Carefully unpack the instrument and accessories. Inspect for damages made in shipment. If any damage is found, notify your **Jenco** representative immediately. All packing materials should be saved until satisfactory operation is confirmed.


VISIONPLUS EC 330 OVERVIEW

A. Meter Description



1. Battery cap
2. LCD screen
3. Keypad
4. Electrode collar
5. Electrode & ATC assembly (Electrode cap is not shown.)

B. LCD Display



1. LOW BATTERY indicator
2. CALIBRATION mode indicator
3. MEASURE mode indicator
4. HOLD mode indicator

5. CONDUCTIVITY/TDS mode indicator
6. CONDUCTIVITY/TDS unit indicator
7. CONDUCTIVITY/TDS reading
8. TEMPERATURE reading
9. TEMPERATURE unit indicator

OPERATION MODES AND KEYPAD OPERATIONS

A. Operation Modes

VisionPlus EC 330 meter has 3 operation modes:

1. Measure Mode. Measure Mode is used to make all conductivity or TDS and temperature measurements.
2. Calibration Mode. Calibration Mode is used to perform 1 or 2 point calibration.
3. Hold Mode. Hold Mode is used to display the locked reading for increased ease of use.


B. Keypad Operations

Key	Operation Mode	Duration	Function
Hold	Measure	0 second	Holds current measurement reading. Press again to resume measuring.
	Hold	0 second	Returns to Measure Mode.
	Measure	5 second	. Erases all stored data.
Cal	Measure	0 second	Enters Calibration Mode.
On/Off	All	0 second	Turns meter on/off.
Mode	Measure	0 second	Selects display mode: conductivity (), conductivity (), TDS() and TDS().

BEFORE YOUR FIRST USE

A. Insert Batteries

1. Remove the battery cover at the top of the unit.
2. Insert the set of batteries (included) ensuring correct polarities.
3. Securely replace battery cover.



B. Soak the Electrode

1. Remove the electrode cap covering the VisionPlus EC 330 meter.
2. Soak the electrode in distilled water for 10 minutes before first use or after storage.

C. Preparing Standard Solutions

Suitable conductivity standards are available commercially or the user can prepare them using research grade reagents.

Here are some standard solutions the user can prepare to calibrate the probe of the model EC330.

1. Standard solution of 1413uS at 25 : Accurately weight out 0.746 grams of research grade dried Potassium Chloride (KCL). Dissolve in 1000ml of distilled water.
2. Standard solution of 12.90mS at 25 : Accurately weight out 7.4365 grams of research grade dried Potassium Chloride (KCL). Dissolve in 1000ml of distilled water.

[Note: You can store the remaining solution in a plastic container for one week but the air space between the cap and the solution must be kept to an absolute minimum. Storing the excess solution below 4 can increase the storage life. If you have any doubt of the accuracy of the stored solution, a fresh batch should be prepared.]

D. Setup and Calibrate the Electrode and Meter

VisionPlus EC 330 must be setup and calibrated before your first use. Please follow the instructions detailed in section **USING VISIONPLUS EC 330**.

USING VISIONPLUS EC 330

A. Power On/Off

Press the "On/Off" key to turn the unit on. If the unit is running then you can press the "On/Off" key to turn the unit off. The unit will automatically turn off after 10 minutes of no key activity.

[Note: The unit will not automatically shut off if it is still immersed in solution even after 10 minute of no key activity.]

B. Calibrate Conductivity

The user can select one or two point conductivity calibration.

1. Rinse the electrode & ATC assembly in distilled water and immerse them in the standard solution of 1413uS. The temperature displayed is the solution temperature.
2. Press "Cal" key to initiate calibration. The "CAL" icon will appear when the main display shows "1415". **Single Point** calibration is now complete. The "MEAS" icon will appear. The unit is now ready to measure.

[Note: At this moment, the unit can measure 0~2000uS range of conductivity.]

3. Remove the electrode & ATC assembly from the standard solution of 1413uS. Rinse them in distilled water and immerse them in the standard solution of 12.90mS. The unit will display the temperature of the standard solution of 12.90mS.
4. Press "Cal" key to initiate calibration. The "CAL" icon will appear when the main display shows "12.90". **Dual Points** calibration is now complete. The "MEAS" icon will appear. The unit is now ready to measure.

[Note: At this moment, the unit can measure 0.0~20.00mS range of conductivity.]

C. Measure

In the "Measure Mode", dip the meter into the test solution. Measuring for Conductivity () commences. Press "Mode" key to select: Conductivity(), Conductivity(), TDS() and TDS().


[**Note:** If the "CAL" icon does not appear, during measuring, it means the unit has not been calibrated. Repeat the calibration procedure.]

D. Hold Data


1. When the conductivity reading is stable, press "Hold" key once to lock the reading.
2. Press "Hold" key again to unlock reading and the unit will return to "Measure Mode". The unit is now ready for another measurement.


REPLACE ELECTRODE

1. Unscrew the electrode collar to remove the electrode & ATC assembly as shown in the right figure.
2. Remove the old electrode from the electrode collar.
3. Insert a new electrode, make sure the electrode fit back into the meter correctly.
4. Screw back the electrode collar.
5. Soak the electrode in distilled water for 10 minutes and recalibrate the EC 330 following the instructions detailed in section **USING VISIONPLUS EC 330..**



REPLACE THE OLD BATTERIES

Replace the battery when the blinking low battery indicator “” appears on the upper left corner of the LCD screen. The instrument can operate within specifications for approximately 2~3 hours after low battery indicator appears.



1. Take off the battery cover.
2. Remove all of the old batteries and insert a new set of batteries ensuring the polarities are correct.

[Note: Calibration of the unit is required after replacement of batteries.]

ERROR DISPLAYS AND TROUBLESHOOTING

Conductivity LCD Display	ATC Display	DISPLAY Mode	Possible cause(s) [Action(s)]
"OVER"	"OVER"	Measure	Temperature >99.9°C range. [Bring solution to a lower temperature.] [Replace electrode & ATC assembly.]
"OVER"	"udr"	Measure	Temperature <0.0°C range. [Bring solution to a higher temperature.] [Replace electrode & ATC assembly.]
"OVER"	60.0 ~ 99.5°C	Measure	Temperature >60.0°C, over the temperature compensation range. [Bring solution to a lower temperature.]
"OVER"	0.0 ~ 60.0°C	Measure	[The conductivity value of the test solution is beyond 20mS.] [Replace electrode & ATC assembly.]
"ERR"	/	Calibration	a. Temperature exceed 0 ~ 60.0°C Temperature compensation b. Correction of slope beyond 50%. [Bring solution to a lower temperature.] [Use a new standard solution.] [Replace electrode & ATC assembly.]

SPECIFICATIONS

Conductivity

Range	Resolution	Accuracy
0 to 1990uS	5 uS	±1% FS
2.00 to 19.90mS	0.05mS	±1% FS

TDS

Range	Resolution	Accuracy
0 to 1000mg/L	5 mg/L	±1% FS
1.00 to 10.00g/L	0.05g/L	±1% FS

Temperature

Range	Resolution	Accuracy
0.0 to 99.5 °C 32 to 212 °F	0.5 °C 1 °F	±0.5 °C ±1 °F

Conductivity

Temperature compensation	AUTO 0.0°C to 60.0 °C
Temperature Coefficient	1.91%/°C
Reference temperature	25°C

TDS

TDS Constant	0.50
---------------------	------

Temperature

Temperature sensor	Thermistor, 10 k at 25°C
Temperature unit	°C and °F

General

Power:	LR44 x 4
Battery life:	>100 Hours
Ambient temperature range	0.0 to 50.0 °C
Case	IP67 water-tight case
Weight	105 g

WARRANTY

Jenco warrants this product to be free from significant deviations in material and workmanship for a period of 1 year from date of purchase. If repair or adjustment is necessary and has not been the result of abuse or misuse, within the year period, please return-freight-prepaid and the correction of the defect will be made free of charge. If you purchased the item from our **Jenco** distributors and it is under warranty, please contact them to notify us of the situation. **Jenco** Service Department alone will determine if the product problem is due to deviations or customer misuse.

Out-of-warranty products will be repaired on a charge basis.

RETURN OF ITEMS

Authorization must be obtained from one of our representatives before returning items for any reason. When applying for authorization, have the model and serial number handy, including data regarding the reason for return. For your protection, items must be carefully packed to prevent damage in shipment and insured against possible damage or loss. **Jenco** will not be responsible for damage resulting from careless or insufficient packing. A fee will be charged on all authorized returns.

NOTE: **Jenco** reserves the right to make improvements in design, construction and appearance of our products without notice.

Jenco Instruments, Inc.

7968 Arjons Drive, Suite C

San Diego, CA 92126 USA

TEL: 858-578-2828

FAX: 858-578-2886

E-Mail: jencoinfo@jencoi.com; sales@jencoi.com

Website: www.jencoi.com

Jenco Electronics Inc.

P.O. Box Linkou 117

Taipei, Taiwan

TEL: 886-2-2601-6191

FAX: 886-2-2601-7206

E-Mail: jencoe@ms2.hinet.net

Shanghai Jenco Instruments, Ltd.

18 Wang Dong Zhong Road

Sijing Town, Songjiang

Shanghai, China

TEL: 86-021-5761-9599

FAX: 86-021-5761-9598

E-Mail: jencos@jenco.com.cn

Website: www.jenco.com.cn